

Date Request : 05 MEI 2017

PR #

7	7	1	0	1	7	0	0	1	9
---	---	---	---	---	---	---	---	---	---

Requestor Name : HARDIAN ROMA P. S

Type of Purchase * CAPEX OPEX

Requestor Email : Hardian.siallagan@trakindo.co.id

For CAPEX, select the following type * :

Plant (Branch Code) * : 0B77

CAPEX IT New Building

Department : PPSR

CAPEX

Division : EIA



Reason for Purchase (Including justification for replacement)

REPAIR PENUTUP GENSET CATERPILLAR

Material/ Service# *	Material/ Service Desc*	Mat/Serv Grp.	Qty	UoM	Req. Date	Estimate Price	GL Account	Assign Code*	Acc. Assign #*
M	4 Penutup Genset terdiri :								
	Plat bagian Atas	}							
	Plat bagian Kiri belakang					5.500.000			
	Plat bagian kanan belakang								
	Plat Belakang & Atas								
	By :								
	Bengkel Bayu Ambon								
	Total					5.500.000			

Notes: *Pekerjaan perbaikan penutup genset yang rusak*

Delivery
To support TU Ambon

Requested by	1st Approval	2nd Approval	3rd nd Approval
 Hardian Roma PS PPSR	 Wahyudi Branch Head (In charge)	Signature/Name/Date Human Resource HO **	Signature/Name/Date Title :

--

BENGKEL BAYU

Jln. Bukit Manusela (Lorong Gunung Malintang) - Hp : 0813 43362445

PENAWARAN HARGA

Bersama ini kami berikan penawaran harga untuk perbaikan sbb :

Bagian yang di perbaiki : 4 buah penutup genset (Plat Bagian Atas, Plat Kiri belakang, Plat Kanan Belakang, Plat Belakang, dan Besi bagian bawah) dari genset Caterpillar.
Lokasi : Pelabuhan Perikanan Ambon
Harga : Rp 5.500.000,- (Lima Juta Lima Ratus Ribu Rupiah)

Catatan:

Harga sudah termasuk bahan, dan transport dari dan ke lokasi

Harga belum termasuk pemasangan di genset.

Demikian Penawaran Harga tersebut kami informasikan. Terimakasih.

Ambon, 03 Mei 2017



BAYU

Pemilik Bengkel