

Action Plan

Dec 11, 2017

Machine No : G01
Machine S/N : YAW
Machine Model : 3516
Description : ECM Error
Wo.No :

No	Date	Task	Result	Technician
1		Check disconnect switch battery		
2		Counter check wiring deep sea		
3		Measure power deep when engine start up		
4		Take picture P/N or model deep sea (Current Schematic)		
5		<i>Check Power pada deep sea dan ECM saat Engine On & Off</i>		
6		Check contactor pada deep sea		

Comment:

- Minta schematic deep sea
- Komunikasi ke customer perihal commissioning genset (reference pemasangan Power Deep Sea)

Checked by

Approved by

Date:

Date: