

JOB ASSIGNMENT

INFORMASI PELANGGAN / CUSTOMER INFORMATION

Nama Pelanggan / Customer Name	: PT.Darma Henwa Tbk
Penanggung Jawab / Contact Person	: Mr. Rahmad Baihaki
Alamat / Address	: Kintap Coal Project
Nomor Telepon / Telephone Number	: 082353145094
Model / Serial Number / ID Number	: 14M3 / E9S00393 / GR3046
SMU (Hours)	:

INFORMASI DETAIL PEKERJAAN / JOB DETAIL INFORMATION

Service Order Number	:		
<input checked="" type="checkbox"/> Warranty	<input type="checkbox"/> Rework	<input type="checkbox"/> Revenue	<input checked="" type="checkbox"/> Inter Department
Nama Serviceman dan SN / Serviceman Name and SN	:		
Ferry Firmansyah / 20698			
Anang Trianto / 27262			
Nanda Yusuf Yahya / 10000606			
Penyelesaian Pekerjaan / Target Completion	: 1 Hari		
Kendaraan / Vehicle	: PTTU516 DA8486CD.		

DETAIL PEKERJAAN / JOB OUTLINE


Perform Inspect SOS High CU (COPPER)
& Inspect Circle Drive Leak

CATATAN PENTING / NOTES :

- Serviceman harus melengkapi dokumen Field Operation Report (FOR) dan Service Report saat kembali ke cabang
Serviceman must complete Field Operation Report (FOR) and Service Report when return back to branch
- Komunikasi selama melakukan pekerjaan kepada Field Supervisor atau Foreman
Communicate to Field Supervisor or Foreman during execute a job continuously
- Serviceman harus mengembalikan seluruh literature dan tool yang digunakan dalam keadaan bersih dan baik.
Serviceman must return all literatures and tools in clean and good condition

Assigned By,

Acknowledge By,


 Name : Dodi Sumaryadi
 Date : 07 April 2021
 Field Supervisor / Foreman

Name :
 Date :
 Customer

Name :
 Date :
 Field Serviceman