

# JOB ASSIGNMENT

## INFORMASI PELANGGAN / CUSTOMER INFORMATION

Nama Pelanggan / Customer Name	: Lion.
Penanggung Jawab / Contact Person	: La'OE
Alamat / Address	- Sei Kupang
Ewin.	: 0813 8264 6868
Nomor Telepon / Telephone Number	: 0852 1504 4193
Model and Serial Number	: 3806C / ZBT 781
SMU (Hours)	:

## INFORMASI DETAIL PEKERJAAN / JOB DETAIL INFORMATION

Work Order Number	:
<input type="checkbox"/> Warranty <input type="checkbox"/> Rework <input checked="" type="checkbox"/> Revenue <input type="checkbox"/> Inter Department	
Nama Serviceman dan SN / Serviceman Name and SN	- RIVALDO - IRFAN
Penyelesaian Pekerjaan / Target Completion	:
Kendaraan / Vehicle	:


## DETAIL PEKERJAAN / JOB OUTLINE

- LEAK at ENGINE AREA.  
( Bawa oli engine )

## CATATAN PENTING / NOTES :

- Serviceman harus melengkapi dokumen Field Operation Report (FOR) yang telah ditandatangani Pelanggan dan Service Report saat kembali ke cabang  
*Serviceman must complete Field Operation Report (FOR) acknowledged by Customer and Service Report when return back to branch*
- Komunikasi dan melaporkan perkembangan pekerjaan (lisan dan tertulis) selama melakukan pekerjaan kepada Field Supervisor atau Foreman  
*Communicate and report progress (verbal and written) to Filed Supervisor or Foreman during repair job performed*
- Serviceman harus mengembalikan seluruh literature dan tool yang digunakan dalam keadaan bersih dan baik.  
*Serviceman must return all literatures and tools in clean and good condition*

Assigned By,



Name : MASHAR.  
Date : 25-07-24

Field Supervisor / Foreman

Acknowledge By,

Name :  
Date :

Customer

Name :  
Date :

Field Serviceman