



BERITA ACARA SERAH TERIMA PEKERJAAN
ACCEPTANCE OF JOB

No. _____

Pelanggan : PT. MAMBAKIN BATUBARA
CustomerLokasi : TEMPIRAI
SiteNo Unit Cust : GC 02Modal : 120KSerial Number : SZN 10 259SMU : 12699Pada Hari : SABTU
Day'sTanggal : 04 SEPTEMBER 2021
DateJenis pekerjaan yang telah selesai dikerjakan : COMMISSIONING TRANSMISSION AFTER RECONDITION
Types of work that have been completedDilakukan pada hari : SABTU Tanggal/Date: 04/09/2021 Jam/Hours: _____
Execute at dayDan telah di ujicoba dengan hasil : GOOD (BAIK)
And Has Been Tested with ResultPelanggan yang menyaksikan pekerjaan ini : BAPAK KHAIKUDIN & BAPAK SADAM HUSEN
Customer who viewed this perform:Keterangan :
RemarkReff Service Order # 0600359895 Reff PO _____Demikian Berita Acara Serah Terima Pekerjaan ini dibuat untuk dapat dipergunakan sebagaimana mestinya.
Thus the Job handover event letter is made to be used properlyDiterima Oleh / Receive by,
Pelanggan/Customer
Nama/Name Zarnal AS
Jabatan/Position _____

Pelaksana / Executor,

PT Trakindo Utama


Nama/Name P. Denny Ieko N
Jabatan/Position _____

PT Trakindo Utama

Gedung TMT 1, 11-17th Floor
 Jl. Cilandak KKO No. 1 Jakarta 12560
 Tel. (62-21) 7822373
 Fax. (62-21) 7822357, 7822379
 www.trakindo.co.id

FIELD OPERATION REPORT

Date :
 Contact :
 Email :

NPWP No. 02.025.873.7-091.000

105747

Serviceman

KAMPUS

Name : P. Donny T	Salary No : 10398	Date : 02-09-2021
-------------------	-------------------	-------------------

Customer

Name : PT. MANDIRIANBAH BAWABARA	Site : TEMPURAI
----------------------------------	-----------------

Machine / Engine

Model : 120K	Plant No : GC 02	Serial No : SN 6259	SMU : 12699
--------------	------------------	---------------------	-------------

Work Order : 8600359895	Job Outline : Commissioning TRANS After Recondition
-------------------------	---

Time Record


CLOCK TIME		DESCRIPTION	SEG	OPR	HOURS & MINS
START	FINISH				
09:00	10:00	Prepare tool and Vehicle			2-15
10:00	13:00	Travel to site Penunggalan Kup			3-15
13:00		Mealtime. Break to Cirebon Street			
		Travel to site Tempurai PT. MBB			
		Contact Customers			4-15
	17:00	Safety Induction			
Total					8-15

Travel Expense	Amount
Chg Code :	Rp.
Category	
Daily Business	350.000
Departure/Arrival	/
Transport Cash	
Other	
Total	350.000

TRANSPORT
Chg Code :
Vehicle Type :
Rate/Km :
Actual Km :

CUSTOMER ACKNOWLEDGEMENT	
The Above Work, subject to PTU	
Terms & Condition, has been completed to our satisfaction	
Name (in capital):	Signed:
Zand A	

Customer Comments



PT Trakindo Utama

FIELD OPERATION REPORT

Gedung TMT 1, 11-17th Floor
Jl. Cilandak KKO No. 1 Jakarta 12560
Tel. (62 21) 7822373
Fax. (62-21) 7822357, 7822379
www.trakindo.co.id

Date :
Contact :
Email :

NPWP No. 02.025.873.7-091.000

105748

Serviceman

Name : P-Denny T Salary No : 10398 Date : 03-09-2021

Customer

Name : DE MANDIRYATI BATUBARA Site : TEMPIRAH

Machine / Engine

Model : 1201C Plant No : 6C 02 Serial No : SZN 102 59 SMU : 12699

Work Order : 8600359895 Job Outline : Commissioning TRAK After Recondition

Time Record

CLOCK TIME		DESCRIPTION	SEG	OPR	HOURS & MINS
START	FINISH				
0700		waiting customer completed component TRANSMISSION, FUEL TANK and RADIATOR			9.0
		waiting customer completed claim			
	1700	customer information commissioning Next Day			
Total					9.0

Travel Expense	Amount
Chg Code :	Rp.
Category	
Daily Business	350.000
Departure/Arrival	/
Transport Cash	/
Other	
Total	350.000

TRANSPORT
Chg Code :
Vehicle Type :
Rate/Km :
Actual Km :

Total

CUSTOMER ACKNOWLEDGEMENT

The Above Work, subject to PTU
Terms & Condition, has been completed to our satisfaction

Name (In capitals): Zainal AS

Signed:

Customer Comments

PT Trakindo Utama

Gedung TMT 1, 11-17th Floor
 Jl. Cilandak KKO No. 1 Jakarta 12560
 Tel. (62-21) 7822373
 Fax. (62-21) 7822357, 7822379
 www.trakindo.co.id

FIELD OPERATION REPORT

Date :
 Contact :
 Email :

NPWP No. 02.025.873.7-091.000

105749

Serviceman

Name : P-Danny	Salary No : 10398	Date : 04-09-2021
----------------	-------------------	-------------------

Customer

Name : PT MARDIANGIN BATUBARA	Site : TEMPILAH
-------------------------------	-----------------

Machine / Engine

Model : 120 K	Plant No : GC 02	Serial No : SZN/D259	SMU : 12699
---------------	------------------	----------------------	-------------

Work Order : 8600359895	Job Outline : Commissioning Teras After Recondition
-------------------------	---

Time Record

CLOCK TIME		DESCRIPTION	SEG	OPR	HOURS & MINS
START	FINISH				
0700		Check Amalams Cartr Move			
		Check Transmission Error by ET Tool			
		Found Solenoid Transmission current Below Normal (All Solenoid)			
		Check wiring Harness found socket All Solenoid wiring install Repair OK			10.00
		Check oil filter, replace Temp Sensor Voltage above Normal. Clean up Socket OK.			
		Performing final Full calibration Transmission OK (Success) and test machine operation OK			
	1800	Monitor and operation			
Total					10.00

Travel Expense	Amount
Chg Code :	Rp.
Category	
Daily Business	350.000
Departure/Arrival	
Transport Cash	1
Other	
Total	350.000

TRANSPORT
Chg Code :
Vehicle Type :
Rate/Km :
Actual Km :

CUSTOMER ACKNOWLEDGEMENT:	
The Above Work, subject to PTU Terms & Condition, has been completed to our satisfaction	
Name (In capitals):	Signed:
Zaidul As	

Customer Comments



PT Trakindo Utama
 Southern Sumatera
 Jl. Lingkar Barat II, Kel. Bagan Pete
 Kec. Alam Barajo, Jambi 36129 - Indonesia
 Tel. (62-741) 443 749
 Fax. (62-741) 443 749
 www.trakindo.co.id

FIELD OPERATION REPORT

Date :
 Contact :
 Email :

NPWP No. 02.025.873.7-091.000

403520

Serviceman

Name : *Eko. Melzandi* Salary No : *10000707* Date : *subtu 0-T 04-09-2021*

Customer

Name : *pt. Mandarjati Batu Bara* Site : *Tempirai*

Machine / Engine

Model : *170k* Plant No : Serial No : *S 2U 10259* SMU : *12699*

Work Order : *Q 600 359 993* Job Outline : *Commissioning Transmission After Recondition*

Time Record

CLOCK TIME		DESCRIPTION	SEG	OPR	HOURS & MINS
START	FINISH				
<i>07.00</i>		<i>- Check Machine Can't Move. Ⓟ</i>			
		<i>- Check transmission Error By ET: 700 G</i>			
		<i>- Found Solenoid transmission current below normal (All Solenoid)</i>			
		<i>- check wiring harness found socket All Solenoid wrong install Repair - ok.</i>			<i>100</i>
		<i>- check oil Transmission Temp. sensor Voltage above normal. Clean up socket - ok.</i>			
		<i>- Perform Timing fill calibration transmission ok. (Success) and test Machine operation. ok.</i>			
	<i>18.00</i>	<i>- Make Report and Reset monitor unit.</i>			
		Total			<i>100</i>

Travel Expense	Amount
Chg Code :	Rp.
Category	
Daily Business	<i>350.000</i>
Departure/Arrival	
Transport Cash	
Other	
Total	<i>350.000</i>

TRANSPORT
Chg Code :
Vehicle Type :
Rate/Km :
Actual Km :

CUSTOMER ACKNOWLEDGEMENT:	
The Above Work, subject to PTU	
Terms & Condition, has been completed to our satisfaction	
Name (In capitals):	Signed:
<i>Zainal AS</i>	<i>[Signature]</i>

Customer Comments

Cabang/ Branch:

JAMBI

Tanggal / Date:

04-09-2021

SO Number

8600359895



TANGGAPAN PELANGGAN untuk TEKNISI
Customer Feedback for Technician

PERTANYAAN Question	NILAI Rating
1. Seberapa cepat Trakindo dalam penyelesaian pekerjaan? <i>How fast Trakindo finish the job?</i>	☆☆☆☆✓
2. Seberapa cepat Trakindo merespon permintaan anda? <i>How fast Trakindo response to your request?</i>	☆☆☆☆✓
3. Seberapa puas Anda dengan kualitas produk dan layanan Trakindo? <i>How satisfied are you with the quality product or service from Trakindo?</i>	☆☆☆☆✓
4. Secara keseluruhan bagaimana kepuasan anda terhadap layanan Trakindo? <i>In overall how satisfy are you with the service delivered by Trakindo?</i>	☆☆☆☆✓
5. Komentar / Comments :	
<hr/> <hr/> <hr/>	

Nama Teknisi
Technician Name

Technician 1: Technician 3:

Technician 2: Technician 4:

DATA PELANGGAN
Customer Information

Nama / Name:

Perusahaan / Company:

No. Tlp / Phone Number:

Tanda tangan / Signature: